

● PRINTER RUSH ●

(PTO ASSISTANCE)

Application : <u>09/535045</u>	Examiner : <u>Nguyen</u>	GAU : <u>2671</u>	
From : <u>FE</u>	Location : <u>IDC</u> FMF FDC	Date : <u>9-27-05</u>	
Tracking #: <u>EPM - 09/535045</u>		Week Date: <u>7-25-05</u>	

DOC CODE	DOC DATE	MISCELLANEOUS
<input type="checkbox"/> 1449		<input type="checkbox"/> Continuing Data
<input type="checkbox"/> IDS		<input type="checkbox"/> Foreign Priority
<input type="checkbox"/> CLM		<input type="checkbox"/> Document Legibility
<input type="checkbox"/> IIFW		<input type="checkbox"/> Fees
<input type="checkbox"/> SRFW		<input type="checkbox"/> Other
<input checked="" type="checkbox"/> DRW	<u>3-24-00</u>	
<input type="checkbox"/> OATH		
<input type="checkbox"/> 312		
<input type="checkbox"/> SPEC		

[RUSH] MESSAGE: ATTN: Chief DRAFTSPERSON
Requesting New Drawing sheet for
Fig. 2-Serial number impinging
on drawing.

Thank You

[XRUSH] RESPONSE: _____

DRAWINGS CORRECTED

10/4/2005

INITIALS: CSJ

NOTE: This form will be included as part of the official USPTO record, with the Response document coded as XRUSH.
 REV 10/04

004220-5405560





Figure 1
Prior Art

005505500-0220



216







Figure 3


212



400



402



404

continued on next page

Figure 4




Figure 5